

**U.S. EPA Region 3  
Air Monitoring Quality Assurance Workshop  
June 25 – 26, 2014  
1650 Arch Street  
Philadelphia PA, 19103**

<b>Wednesday, June 25, 2014</b>		
10:30am – 10:40am	Welcome & Introductions	Kia Hence, R3
10:40am – 11:00am	Fitting in: How does your data fit into the big picture.	Alice Chow, R3
11:00am – 12:00pm	Appendix A and EPA DASC tool	Mike Papp, OAQPS
<b>12:00pm – 1:00pm</b>	<b>Lunch</b>	
1:00pm – 1:10pm	Zero Drift	Mike Papp, OAQPS
1:10pm – 1:30pm	CSN Data Validation	Beth Landis, OAQPS
1:30pm – 2:30 pm	Meta Data and Near Road	Tim Hanley, OAQPS
<b>2:30pm – 2:45pm</b>	<b>Break</b>	
2:45pm – 3:45pm	AQS	Robert Coats, OAQPS
3:45pm – 4:30pm	Questions and Answers (Panel Discussion)	Mike Papp Tim Hanley Robert Coats
<b>Thursday, June 26, 2014</b>		
8:30am – 9:15am	TSA Findings / Philadelphia Demonstration on Remote Station Access	Kia Hence, R3 Paresh Mehta, AMS Lab
9:15am – 10:00am	QA/QC of Meteorological Equipment and Meteorological Data	Howard Schmidt, R3
<b>10:00am – 10:15am</b>	<b>Break</b>	
10:15am – 11:15am	Ozone Certification Procedures, Flow Verifications, TTP systems Certifications and Protocol gas Verifications (PGVP)	Avi Teitz, R2 Mustafa Mustafa, R2
11:15am – 12:30pm	Data Validation, Data Completeness, Data Review and Data Handling	Pauline DeVose, R3 Kia Hence, R3 Loretta Hyden, R3 Howard Schmidt, R3